



Invoice No.  
**34020**

Page 1  
Order Date 11/11/17 03:40 pm  
Paid: 12/02/17 02:01 pm

1524 Spring Hill Road Unit H,S  
Mclean, Va 22102  
Phone: 703-242-8680 FAX: 703-242-0358

Ref: 895-CWCTHUR

**WWW.INTERSPORTPERFORMANCE.COM**



**77 Porsche 911 red**  
86 10 Mi.  
Uc: DPD 1165 H8Cyl Eng  
Mn: 911720152212/76  
iEq:ACPSFI

Quotes

1 11/11/17 03:44pm14085.00  
Peter by phone 202-588-1009

full check over on vehicle  
full write up on vehicle, what needs immediate attention, what can wait down road  
verify oil leaks  
leak downs?  
**202-588-6555 WORK CLAIRE**

**IJb01 CHECK OVER** Labor: 0.00 hrs@S144.00/h;;so.ool

CHECK OVER VEHICLE

Status: Completed Tech: Craig W.

**Job Subtotal: \$0.00**

**IJob02.TORQUE HEAD STUDS** 2.00 hrs@\$144.00/hr=\$288.00

INSPECT FOR BROKEN HEADSTUD, SERVERAL FOUND NOT TORQUED TO SPEC. RETORQUE ALL 24 HEAD STUDS TO CHECK FOR PULLED OR BROKEN STUDS. ALL HEAD STUDS ARE GOOD AT THIS TIME AND ARE ALL PROPERLY TORQUED. THIS NEEDED TO BE PERFORMED BEFORE LEAK DOWNS WHERE TESTED.

Status: Completed Tech: Craig W.

**Job Subtotal: \$288.00**

**IJob03.911 VALVE ADJUSTMENT** Labor: 7.00 hrs@\$144.00/hr=\$1,008.00

PK03	VALVE COVER GASKET SET-N	1.0@	69.70 =\$	69.70	
7992	SPARK PLUG-N	6.0@	4.95=\$	29.70	<b>99.40</b>

PERFORM VALVE ADJUSTMENT AND LEAK DOWNS. INSTALL NEW PLUGS

CYL #1-95% CYL#6-95% CYL#2-95% CYL#4-94% CYL #3-95% CYL#S-94%

NOTICE BEGINNIGS OF PITTING ON CYL #4 CAMSHAFT INTAKE LOBE. CYL#1 EXHAUST ROCKERSHAFT IMPROPERLY LOCATED.

Status: Completed Tech: Craig W.

**Job Subtotal: \$1,107.40**

----->----->----->---Continu d on the next page--->----->----->----->





Invoice No.  
**34020**

Page 3  
Order Date 11/11/17 03:40 pm  
Paid: 12/02/17 02:01 pm

1524 Spring Hill Road Unit H,S  
McLean, Va 22102  
Phone: 703-242-8680 FAX: 703-242-0358

Ref: 895-CWCTHUR

[WWW.INTERSPORTPERFORMANCE.COM](http://WWW.INTERSPORTPERFORMANCE.COM)

**Job09 4 WHEEL ALIGNMENT/PORSCHE**

PERFORM FOUR WHEEL ALIGNMENT, SET CAMBER, CASTER AND TOE SETTINGS

Status: Completed Tech: Craig W.

Job Subtotal: \$396.00

**Job10.FRONT BRAKES Labor: 5.00 hrs@\$144.00/hr=\$720.00**

91135142502	BRAKE CALIPER/RF-N	1.0@	373.71 =\$	373.71	
91135142602	BRAKE CALIPER/LF-N	1.0@	373.71 =\$	373.71	
99905909800	WHEEL BEARING-N	2.0@	72.52 =\$	145.04	
99905906500	OUTER WHEEL BEARING-N	2.0@	33.50 =\$	67.00	
477405641	WHEEL SEALS-N	2.0@	16.35 =\$	32.70	
91135295006	BRAKE PAD SET-\$	1.0@	94.34=\$	94.34	
4774050830	BRAKE DISC-\$	2.0@	182.88 =\$	365.76	
90134162300	BEARING ADJ. SPACER-\$	2.0@	70.15 =\$	140.30	1592.56

REMOVE AND REPLACE FRONT BRAKE PADS, CALIPERS AND ROTORS. REPLACE WHEEL BEARINGS AND SEALS. WHILE REPLACING FRONT WHEEL BEARINGS FOUND BEARING SPACERS MISSING. INSTALL NEW BEARING SPACERS.

Status: Completed Tech: Craig W.

Job Subtotal: \$2,312.56

**Job11.911 BRAKE HOSES Labor: 4.00 hrs@\$144.00/hr=\$576.00**

90135563201	HOSE, BRAKE FT.-N	2.0@	73.11 =\$	146.22	
90135563101	HOSE, REAR-N	2.0@	69.70 =\$	139.40	285.62

REMOVE AND REPLACE ALL FOUR RUBBER BRAKE HOSES ON FRONT AND REAR OF VEHICLE.

Status: Completed Tech: Craig W.

Job Subtotal: \$861.62

**Job12.BRAKE MASTER CYLINDER Labor: 4.00 hrs@\$144.00/hr=\$576.00**

91135501112	BRAKE MASTER CYL.-N	1.0@	351.12 =\$	351.12	
113945515H	Swich, Brake-N	2.0 @	43.22 =\$	86.44	437.56

REMOVE AND REPLACE BRAKE MASTER CYLINDER.

Status: Completed Tech: Craig W.

Job Subtotal: \$1,013.56

**Job13 BRAKE FLUSH W/AJE 200 Labor: 1.00 hrs@\$144.00/hr=\$144.00**

----->----->----->----->----->----->----->

Continued on the next page----->----->----->----->



Invoice No.  
**34020**

Page 4  
Order Date 11/11/17 03:40 pm  
Paid: 12/02/17 02:01 pm

1524 Spring Hill Road Unit H,S  
McLean, Va 22102  
Phone: 703-242-8680 FAX: 703-242-0358

Ref: 895-CWCTHUR

[WWW.INTERSPORTPERFORMANCE.COM](http://WWW.INTERSPORTPERFORMANCE.COM)

**Job13 BRAKE FLUSH W/ATE 200**

BF1200	ATE TYP 200-N	1.5@	28.95 =\$	43.43	<b>43.43</b>
--------	---------------	------	-----------	-------	--------------

FLUSH HYDRAULIC BRAKE SYSTEM WITH ATE TYP-200 HIGH TEMP FLUID

Status: Completed Tech: Craig W.

**Job Subtotal: \$187.43**

**Job14 ADJUST PARKING BRAKE**

**Labor: 1.00 hra@S144.00/hr=S144.00**

ADJUST PARKING BRAKE AND CHECK PARKING BRAKE SHOES.

Status: Completed Tech: Craig W.

**Job Subtotal: \$144.00**

**Job15 REAR BRAKES**

**Labor: 2.00 hrs@\$144.00/hr=\$288.00**

90135204114	BRAKE DISC-N	2.0 @	214.97 =\$	429.94	
91135195003	BRAKE PAD SET-N	1.0 @	88.42 =\$	88.42	<b>518.36</b>

REMOVE AND REPLACE REAR BRAKE PADS AND ROTORS.

Status: Completed Tech: Craig W.

**Job Subtotal: \$806.36**

**Job16 WIPER BLADES**

**Labor: 0.00 hrs@\$144.00/hr=\$0.00**

96462890102	WIPER BLADES-N	2.0@	12.55 =\$	25.10	<b>25.10</b>
-------------	----------------	------	-----------	-------	--------------

REMOVE AND REPLACE WIPER BLADES.

Status: Completed Tech: Craig W.

**Job Subtotal: \$25.10**

**Job17 WINDSHIELD WASHER**

**Labor: 1.00 hra@\$144.00/hr=S144.00**

DIAGNOSE WINDSHIELD WASHER SYSTEM; FOUND BAD CONNECTION AT PUMP ALSO CLEANED SQUIRTERS AND AIMED FOR EFFECT

Status: Completed Tech: Craig W.

**Job Subtotal: \$144.00**

----->---->---->---Continued on the next page--->---->----->----->



Invoice No.  
**34020**

Page 5  
Order Date 11/11/17 03:40 pm  
Paid: 12/02/17 02:01 pm

1524 Spring Hill Road Unit H,S  
Mclea11, Va 22102  
Phone: 703-242-8680 FAX: 703-242-0358

Ref: 895-CWCTHUR

**WWW.INTERSPORTPERFORMANCE.COM**

**Job18.HEATER & DEFROSTER BLOWER Labor: 1.00 hrs@\$144.00/hr=\$144.00**

DIAGNOSE HEATER & DEFROSTER BLOWER MOTOR; FIX WIRING ISSUE ON REAR ENGINE BLOWER ONLY BLOWING AT HALF SPEED AND THE FRONT FRESH AIR BLOWER VERY NOISEY. RECOMMEND TO REPLACE BOTH FRONT FRESH AIR BLOWER AND REAR ENGINE HEATER BLOWER.

Status: Completed Tech: Craig W.

**Job Subtotal: \$144.00**

**Job19111 "S" HOSE Labor: 0.50 hrs@\$144.00/hr=\$72.00**

91110723300	S HOSE, OIL-N	1.0@	58.06 =\$	58.06	
20W50	MOTOROIL-N	12.0@	8.99 =\$	107.88	
OC54	OIL FILTER-N	1.0@	20.54 =\$	20.54	<b>186.48</b>

REMOVE AND REPLACE OIL TANK "S" HOSE

Status: Completed Tech: Craig W.

**Job Subtotal: \$258.48**

**Job20.ENGINE SOUND PAD Labor: 2.00 hrs@\$144.00/hr=\$288.00**

91155689101	SOUND PAD-N	1.0@	96.67 =\$	96.67	
3MG	3M GLUE-N	1.0@	47.32 =\$	47.32	<b>143.99</b>

WHILE ENGINE IS OUT OF VEHICLE REMOVE AND REPLACE ENGINE SOUND PAD.

Status: Completed Tech: Craig W.

**Job Subtotal: \$431.99**

**Job21.CAM FEED LINES Labor: 1.00 hrs@\$144.00/hr=\$144.00**

ADJUST CAM FEED LINES SO THAT THEY ARE POSITIONED PROPERLY.

Status: Completed Tech: Craig W.

**Job Subtotal: \$144.00**

**Job22.911.CARRERA FRONT HOOD SHOCKS Labor: 1.00 hrs@\$144.00/hr=\$144.00**

91151133101	HOOD STRUT-N	2.0@	42.05 =\$	84.10	<b>84.10</b>
-------------	--------------	------	-----------	-------	--------------

REPLACED HOOD SHOCKS

----->----->----->---Continued on the next page--->----->----->----->





**Invoice No.**  
**34020**

Order Date 11/11/17 03:40 pm  
Paid: 12/02/17 02:01 pm

1524 Spring Hill Road Unit H,S  
Mclean, Va 22102  
Phone: 703-242-8680 FAX: 703-242-0358

Ref: 895-CWCTHUR

**WWW.INTERSPORTPERFORMANCE.COM**

**Job26 TRANS OUTPUT SEAL**

9995687410	O-RING-S	1.0@	10.11 =\$	10.11	<b>28.11</b>
------------	----------	------	-----------	-------	--------------

REMOVE GUIDE SLEVE REPLACE SEAL FOR OUTPUT SHAFT(MAIN SHAFT) AND O-RING , CLEAN TRANS

Status: Completed Tech: Craig W.

**Job Subtotal: \$172.11**

**Job27 UPPER OIL LEAKS**

**Labor: 3.00 hrs@\$144.00/hr=\$432.00**

99970731440	THERMOSTAT O-RING-N	1.0@	3.95 =\$	3.95	
93010779102	GASKET BREATHER-N	1.0@	7.50 =\$	7.50	
91160623000	SWITCH, OIL PRESURE-N	1.0@	33.68 =\$	33.68	<b>45.13</b>

BREATHER PLATE LEAKING, OIL THERMOSTAT LEAKING, OPS ALSO---CLEANED AFFECTED AREA AND RESEALED WHILE MOTOR OUT- NOT POSSIBLE TO ACCES WITH MOTOR IN!

Status: Completed Tech: Craig W.

**Job Subtotal: \$477.13**

**Job28 SHIFTER COUPLER**

**Labor: 1.00 hrs@\$144.00/hr=\$144.00**

91142402404	SHIFT COUPLER-N	1.0@	118.11 =\$	118.11	<b>118.11</b>
-------------	-----------------	------	------------	--------	---------------

REMOVE AND REPLACE WORN SHIFTER COUPLER AT TRANSMISSION AND TUNNEL. INSPECTED FRONT SHIFTER BUSHING AND FOUND GOOD AT THIS TIME. ADJUSTED SHIFTER BEST AS POSSIBLE. SHIFTS MUCH BETTER AT THIS TIME, FIRST GEAR SYCRO HAS WEAR AND DOES REQUIRING A LITTLE EFFORT TO GET INTO GEAR.

Status: Completed Tech: Craig W.

**Job Subtotal: \$262.11**

**Job29 OIL LINES & MOTORMOUNT WASHERS**

**Labor: 3.00 hrs@\$144.00/hr=\$432.00**

91110773011	OIL LINE-N	1.0@	257.88 =\$	257.88	
91110772910	OIL LINE-N	1.0@	273.83 =\$	273.83	
90130531100	CURVED WASHER-N	4.0@	6.50 =\$	26.00	<b>557.71</b>

REMOVE AND REPLACE BOTH OIL LINES TO THERMOSTAT. INSTALL MISSING MOTOR MOUNT WASHERS.

Status: Completed Tech: Craig W.

**Job Subtotal: \$989.71**

**Job30 Resurface Flywheel**

**Sublet \$166.00**

Send out Flywheel for Resurfacing

----->----->----->----->----->----->----->

**Continued on the next page---**



Invoice No.  
34020

Page 8  
Order Date 11/11/17 03:40 pm  
Paid: 12/02/17 02:01 pm

1524 Spring Hill Road Unit H,S  
McLean, Va 22102  
Phone: 703-242-8680 FAX: 703-242-0358

Ref: 895-CWCTHUR

WWW.INTERSPORTPERFORMANCE.COM

Job30 Resurface Flywheel

Job31 Breather hose Labor: 0.00 hrs@\$144.00/hr=\$0.00

00004320516 OILINE-N 2.0@ 35.85 =\$ 71.70 71.70

REMOVE AND REPLACE BREATHER HOSE AT REAR OF ENGINE WHILE ENGINE IS OUT OF VEHICLE.

Status: Completed Tech: Craig W.

Job Subtotal: \$71.70

Job32 WINDOW REGULATOR Labor: 0.00 hrs@\$144.00/hr=\$0.00

DRIVER SIDE WINDOW REGULATOR LUBED, LUBING REGULATOR HAD A SLIGHT EFFECT ON FUNCTIONALITY HOWEVER THE MANUAL WINDOW REGULATOR WILL NEED TO BE REPLACED TO WORK TO PORSCHE SPEC.

Status: Completed Tech: Craig W.

Job Subtotal: \$0.00

Recommendations: SUNROOF NOT CLOSING ALL THE WAY WILL NEED TO BE DIAGNOSED-CW

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. In no event shall Intersport Performance be liable for any direct, indirect, incidental, punitive, consequential or any other damages whatsoever, whether in action or under contract, tort or otherwise. Under no circumstance, including, but not limited to, negligence, shall Intersport Performance be liable for any damages that result from the use of, or inability to use, the information, materials or products contained in or purchased from this facility. Further, Intersport Performance shall have no liability or responsibility for any delay in the delivery of the vehicle.

Intersport Provides loaner vehicles upon request. I understand that the insurance coverage provided by Intersport is secondary only. Customers's coverage is primary at all times. Intersport will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control. I also agree to pay any & all legal expenses incurred by Intersport as necessary to collect principal & interest on this account as well as expenses incurred in defense of actions arising out of parts & service provided by Intersport. Our warranty is 12k mi or 12 months on all parts & labor whichever comes first. Parts provided by customer. custom fabrication. race/track modifications are not under warranty.

Signature: \_\_\_\_\_

""""Refer a Friend and get 10% off your next factory scheduled interval Service!-

---your feedback( is very important to us!!! So please let me know how we are doing by leaving us a review on Google and Yelp! \_\_\_

- Like us on Facebook! <https://www.facebook.com/IntersportPerformance> ,,,,

----->->->-Continued on the next page--->---->-----?----->





Invoice No.  
**34020**

Page9  
Order Date 11/11/17 03:40 pm  
Paid: 12/02/17 02:01 pm

1524 Spring Hill Road Unit H,S  
Mclean', Va 22102  
Phone: 703-242-8680 FAX: 703-242-0358

Ref: 895-CWCTHUR

[WWW.INTERSPORTPERFORMANCE.COM](http://WWW.INTERSPORTPERFORMANCE.COM)

**Payments to INTERSPORT PERFORMANCE**

**Cost Summary**

Status: Paid Work Order  
  
Payments: \$17,248.49  
1 12/02/17 17248.49 Check 102633126

Labor	10188.00
Parts	6427.21
Sublet	182.00
Haz Waste	0.99
Shop Supplies	48.50
HAZMAT	12.50
Tax	389.29
Total	\$17248.49
Payments	17248.49
Bal Due	0.00

Thank you for choosing INTERSPORT PERFORMANCE