



Check MOT history (<https://www.gov.uk/check-mot-history>)

DRJ886L

TRIUMPH TR6

Colour
Red

Fuel type
Petrol

Date registered
12 October 1990

MOT valid until
20 June 2022

MOT history

Check mileage recorded at test, MOT expiry date, defects and advisories, and view test certificate

Date tested
21 June 2021
PASS

Mileage
77,427 miles

MOT test number
6755 4465 9245

Test location

Expiry date
20 June 2022

Date tested
27 August 2019
PASS

Mileage
76,955 miles

MOT test number
4469 8124 5520

Test location

Expiry date
26 August 2020

Monitor and repair if necessary (advisories):

- **Oil leak, but not excessive (8.4.1 (a) (i))**

Date tested
16 August 2019
FAIL

Mileage
76,925 miles

MOT test number
4812 5144 2012

Test location

Repair immediately (major defects):

- **Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**

Monitor and repair if necessary (advisories):

- **Oil leak, but not excessive (8.4.1 (a) (i))**

Date tested
13 June 2018

PASS

Mileage
75,322 miles

Test location

MOT test number
3000 4667 9209

Expiry date
12 June 2019

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity – dangerous, major, and minor.

Date tested
14 July 2016

PASS

Mileage
75,318 miles

Test location

MOT test number
4382 0707 4649

Expiry date
13 July 2017

Advisory notice item(s)

- **Nearside Play in steering rack inner joint(s) ()**
- **Nearside Front wheel bearing has slight play (2.5.A.3c)**

Date tested
13 July 2016

FAIL

Mileage
75,318 miles

Test location

MOT test number
7476 0706 9176

Reason(s) for failure

- **Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**
- **Windscreen washer provides insufficient washer liquid (8.2.3)**
- **Nearside Stop lamp not working (1.2.1b)**
- **Brake pedal anti-slip provision missing (3.3.A.1b)**
- **Indicator tell tale inoperative (1.4.A.2a)**

Advisory notice item(s)

- **Nearside Play in steering rack inner joint(s) ()**
- **Nearside Front wheel bearing has slight play (2.5.A.3c)**

Date tested
9 July 2015

PASS

Mileage
75,318 miles

Test location

MOT test number
5584 3009 5188

Expiry date

8 July 2016

Advisory notice item(s)

- **Steering system has slight free play detected at steering wheel (2.2.A.1b)**
- **Play in steering rack inner joint(s)**

Date tested
8 September 2014**PASS**Mileage
75,388 miles

Test location

MOT test number
5192 7115 4274Expiry date
7 September 2015Date tested
28 May 2010**PASS**Mileage
76,277 miles

Test location

MOT test number
4733 4894 0118Expiry date
31 May 2011Date tested
1 June 2009**PASS**Mileage
75,787 miles

Test location

MOT test number
5920 1255 9192Expiry date
31 May 2010

Advisory notice item(s)

- **Nearside Rear Shock absorber has a light misting of oil (2.7.3)**
- **Offside Rear Shock absorber has a light misting of oil (2.7.3)**
- **brake pedal bush worn.**
- **slight wear in steering rack ends.**

Date tested
1 June 2009**FAIL**Mileage
75,787 miles

Test location

MOT test number
2245 7225 9194

Reason(s) for failure

- **Brake pedal anti-slip provision missing (3.3.A.1b)**
- **Nearside Headlamp aim too high (1.8)**
- **Offside Headlamp aim too high (1.8)**

Advisory notice item(s)

- **Nearside Rear Shock absorber has a light misting of oil (2.7.3)**

- **Offside Rear Shock absorber has a light misting of oil (2.7.3)**
- **Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**
- **brake pedal bush worn.**
- **slight wear in steering rack ends.**

Date tested
30 May 2008
PASS

Mileage
74,434 miles

MOT test number
5326 8165 8134

Test location

Expiry date
29 May 2009

Outstanding vehicle recalls

Check if TRIUMPH TR6 DRJ886L has outstanding recalls

